

VCDS

Windows Based VAG/VAS Emulator Running on Windows 10 x64

VCDS Version: Release 15.7.4(x64) Data version: 20160216

www.Ross-Tech.com

Dealer/Shop Name:

Workshop Code: 000 00000 000000

Self-Diagnosis Log

Friday,03,June,2016,18:18:01:25034

VIN: XW8ZZZ3CZ9G000175 License Plate:

Mileage: 140420km-87252mi Repair Order:

Chassis Type: 3C (3C0)

Scan: 01 02 03 08 09 10 15 16 17 19 25 42 44 46 52 53 55 56 62 72

VIN: XW8ZZZ3CZ9G000175 Mileage: 140420km-87252miles

01-Engine -- Status: Malfunction 0010

02-Auto Trans -- Status: OK 0000

03-ABS Brakes -- Status: OK 0000

04-Steering Angle -- Status: OK 0000

08-Auto HVAC -- Status: Malfunction 0010

09-Cent. Elect. -- Status: Malfunction 0010

10-Park/Steer Assist -- Status: OK 0000

15-Airbags -- Status: Malfunction 0010

16-Steering wheel -- Status: OK 0000

17-Instruments -- Status: OK 0000

19-CAN Gateway -- Status: OK 0000

25-Immobilizer -- Status: OK 0000

42-Door Elect, Driver -- Status: OK 0000

44-Steering Assist -- Status: OK 0000

46-Central Conv. -- Status: OK 0000

52-Door Elect, Pass. -- Status: OK 0000

53-Parking Brake -- Status: OK 0000

55-Headlight Range -- Status: OK 0000

56-Radio -- Status: OK 0000

62-Door, Rear Left -- Status: OK 0000

72-Door, Rear Right -- Status: OK 0000

VCDS
Self-Diagnosis Log
Friday, 03, June, 2016, 18:18:01:25034
Page 2

VIN: XW8ZZZ3CZ9G000175 License Plate:

Address 01: Engine () Labels: 06J-907-115-BZB.clb
Part No SW: 06J 906 026 A HW: 06J 906 026
Component: MED17.5 2445
Revision: A8H03--- Serial number: VWZCZ000000000
Coding: 0404000319070160
Shop #: WSC 00028 028 00001
VCID: 285418DA9B92D17E16-807C

4 Faults Found:

008581 - Engine Coolant Temp Sensor on Radiator Outlet (G83)
P2185 - 000 - Signal too High - Intermittent

Freeze Frame:

Fault Status: 00100000
Fault Priority: 0
Fault Frequency: 33
Reset counter: 255
Mileage: 138590 km
Time Indication: 0
Date: 2016.04.27
Time: 19:21:52

Freeze Frame:

RPM: 1038 /min
Load: 7.8 %
Speed: 49.0 km/h
Temperature: 106.0°C
Temperature: 38.0°C
Absolute Pres.: 1010.0 mbar
Voltage: 13.716 V

001056 - Catalyst System; Bank 1
P0420 - 000 - Efficiency Below Threshold - Intermittent

Freeze Frame:

Fault Status: 00100000
Fault Priority: 0
Fault Frequency: 1
Reset counter: 255
Mileage: 138959 km
Time Indication: 0
Date: 2016.05.01
Time: 16:24:46

Freeze Frame:

RPM: 2102 /min
Load: 34.5 %
Speed: 99.0 km/h
Temperature: 98.0°C
Temperature: 26.0°C
Absolute Pres.: 1000.0 mbar
Voltage: 13.970 V

006481 - Radiator Fan 2 (V177)

VCDS
Self-Diagnosis Log
Friday,03,June,2016,18:18:01:25034
Page 3

VIN: XW8ZZZ3CZ9G000175 License Plate:

P1951 - 000 - Movement Restricted / Jammed - Intermittent
Freeze Frame:

Fault Status: 00100000
Fault Priority: 0
Fault Frequency: 5
Reset counter: 255
Mileage: 140327 km
Time Indication: 0
Date: 2016.06.02
Time: 17:46:10

Freeze Frame:

RPM: 1419 /min
Load: 9.8 %
Speed: 66.0 km/h
Temperature: 102.0°C
Temperature: 44.0°C
Absolute Pres.: 1000.0 mbar
Voltage: 13.843 V

006480 - Radiator Fan (V7)

P1950 - 000 - Movement Restricted / Jammed - Intermittent
Freeze Frame:

Fault Status: 00100000
Fault Priority: 0
Fault Frequency: 2
Reset counter: 255
Mileage: 140335 km
Time Indication: 0
Date: 2016.06.02
Time: 18:01:19

Freeze Frame:

RPM: 0 /min
Load: 0.0 %
Speed: 0.0 km/h
Temperature: 109.0°C
Temperature: 55.0°C
Absolute Pres.: 1000.0 mbar
Voltage: 12.573 V

Readiness: 0000 0000

VCDS
Self-Diagnosis Log
Friday,03,June,2016,18:18:01:25034
Page 4

VIN: XW8ZZZ3CZ9G000175 License Plate:

Address 02: Auto Trans Labels: 09G-927-750.clb
Part No SW: 09G 927 750 JJ HW: 09G 927 750 JJ
Component: AQ 250 6F 1178
Revision: 00H76000 Serial number:
Coding: 0000328
Shop #: WSC 00028 028 00001
VCID: 02006A725D6EDB2E68-8056

No fault code found.

Address 03: ABS Brakes Labels: 3C0-614-109-C4.clb
Part No SW: 3C0 614 109 P HW: 3C0 614 109 P
Component: J104 C4 440 V2 0011
Revision: --025--- Serial number: 00000785632310
Coding: 0004427
Shop #: WSC 00028 028 00001
VCID: 2B5EE7D68A64FA66FB-807E

No fault code found.

Address 08: Auto HVAC Labels: 3C0-907-044.lbl
Part No SW: 3C0 907 044 DC HW: 3C0 907 044 DC
Component: ClimatronicPQ46 132 0811
Revision: 00132023 Serial number: 0000000000000000
Shop #: WSC 00000 000 00000
VCID: 65CA51EEAC000C16ED-8030

1 Fault Found:

01810 - Actuating Motor for Temperature Flap; Right (V159)

000 - - - Intermittent

Freeze Frame:

Fault Status: 00100000

Fault Priority: 3

Fault Frequency: 124

Reset counter: 78

Mileage: 136791 km

Time Indication: 0

Date: 2016.03.25

Time: 09:17:16

VCDS
Self-Diagnosis Log
Friday,03,June,2016,18:18:01:25034
Page 5

VIN: XW8ZZZ3CZ9G000175 License Plate:

Address 09: Cent. Elect. Labels: 3C0-937-049-30-H.lbl
Part No SW: 3C0 937 049 AL HW: 3C0 937 049 AL
Component: Bordnetz-SG H54 2202
Revision: 00H54000 Serial number: 01000005702820
Coding: E7868F0700041A00470A00000F0000000000F5D435C0001200000000000000
Shop #: WSC 00028 028 00001
VCID: 73EE3FB612D4E2A673-8026

Subsystem 1 - Part No: 3C1 955 419 A Labels: 1KX-955-119.CLB
Component: Wischer 080408 003 0205
Coding: 00046997
Shop #: WSC 00028

Subsystem 2 - Part No: 1K0 955 559 AF Labels: 1K0-955-559-AF.CLB
Component: RLS 190508 046 0204
Coding: 00208933
Shop #: WSC 00028

1 Fault Found:

00924 - Relay for Headlamp Cleaning System (J39)

009 - Open or Short to Ground

Freeze Frame:

Fault Status: 01101001
Fault Priority: 4
Fault Frequency: 1
Reset counter: 45
Mileage: 137476 km
Time Indication: 0
Date: 2016.04.06
Time: 10:12:00

Freeze Frame:

ON
Voltage: 14.35 V
ON
ON
OFF
OFF
OFF

VCDS
Self-Diagnosis Log
Friday,03,June,2016,18:18:01:25034
Page 6

VIN: XW8ZZZ3CZ9G000175 License Plate:

Address 10: Park/Steer Assist (J446) Labels: 3C8-919-475.clb
Part No SW: 3C8 919 475 HW: 3C8 919 475
Component: PARKHILFE 8K H07 0007
Revision: ----- Serial number: 97530812602160
Coding: 100102
Shop #: WSC 00028 028 00001
VCID: 71E235BEA8C8D0B681-8024

No fault code found.

Address 15: Airbags Labels: 5N0-959-655.lbl
Part No SW: 5N0 959 655 A HW: 5N0 959 655 A
Component: J234__005 VW10 HI 1815
Revision: 19013000 Serial number: 0039DP93YFD
Coding: 0012341
Shop #: WSC 00028 028 00001
VCID: 3B7ED7967A046AE66B-806E

Subsystem 1 - Serial number: 6333FTS653611128

Subsystem 2 - Serial number: 6343FTS664151148

Subsystem 3 - Serial number: 6353ETS6QEAATVNP

Subsystem 4 - Serial number: 6363ETS6UOJ9TVNH

Subsystem 5 - Serial number: 000000000000000000

Subsystem 6 - Serial number: 000000000000000000

1 Fault Found:

00532 - Supply Voltage B+

002 - Lower Limit Exceeded - Intermittent

Freeze Frame:

Fault Status: 00100010

Fault Priority: 3

Fault Frequency: 1

Reset counter: 215

Mileage: 136791 km

Time Indication: 0

Date: 2016.03.25

Time: 14:49:45

VCDS
Self-Diagnosis Log
Friday,03,June,2016,18:18:01:25034
Page 7

VIN: XW8ZZZ3CZ9G000175 License Plate:

Address 16: Steering wheel Labels: 3C0-953-549-SW20.lbl
Part No SW: 3C0 953 549 AC HW: 3C0 953 549 AC
Component: J0527 0020
Revision: 00026000 Serial number: 3C5953507AR
Coding: 0001111
Shop #: WSC 00028 028 00001
VCID: 6DDA29CE74F03456A5-8038

Subsystem 1 - Part No: XXXXXXXXXXXX
Component: E0221 002 0010

No fault code found.

Address 17: Instruments Labels: 3C0-920-xxx-17.lbl
Part No SW: 3C0 920 871 D HW: 3C0 920 871 D
Component: KOMBIINSTRUMENT VD1 1216
Revision: V0002000 Serial number: 00000000000000
Coding: 0005105
Shop #: WSC 12345 123 999999
VCID: 254A11EEEC80CC162D-8070

No fault code found.

Address 19: CAN Gateway Labels: 3C0-907-530-V2.clb
Part No SW: 3C0 907 530 H HW: 3C0 907 951
Component: J533_Gateway H13 0142
Revision: H13 Serial number: 2600P084280212
Coding: FDA17F060002021002
Shop #: WSC 00028 028 00001
VCID: 264816E29186C70E24-8072

No fault code found.

Address 25: Immobilizer Labels: 3C0-959-433-25.clb
Part No SW: 3C0 959 433 R HW: 3C0 959 433 R
Component: IMMO 042 0383
Revision: 00042000 Serial number: VWZCZ000000000
Shop #: WSC 131071 1023 2097151
VCID: 3972CD9E703858F679-806C

Subsystem 1 - Part No: 3C0 905 861 G
Component: ELV 027 0380
3C0905861G ELV 027 0380

No fault code found.

VCDS
Self-Diagnosis Log
Friday,03,June,2016,18:18:01:25034
Page 8

VIN: XW8ZZZ3CZ9G000175 License Plate:

Address 42: Door Elect, Driver Labels: 1K0-959-701-MIN3.lbl
Part No SW: 1K0 959 701 AC HW: 1K0 959 793 N
Component: J386 TUER-SG FT 1517
Revision: 72009005 Serial number: 00000073188516
Coding: 0000245
Shop #: WSC 00028 028 00001
VCID: 6FE633C67EFCC64697-803A

No fault code found.

Address 44: Steering Assist Labels: 1Kx-909-14x-44.clb
Part No: 1K1 909 144 M
Component: EPS_ZFLS KI.135 H08 1901
Shop #: WSC 00028 028 00001
VCID: 356AC1AE5C20BC969D-8060

No fault code found.

Address 46: Central Conv. Labels: 3C0-959-433-46.clb
Part No SW: 3C0 959 433 R HW: 3C0 959 433 R
Component: KSG PQ46 ELV 042 0472
Revision: 00042000 Serial number: VWZCZ000000000
Coding: 00910A0001860E763004941570084FCE707801
Shop #: WSC 00028 028 00001
VCID: 3972CD9E703858F679-806C

Subsystem 1 - Part No: 1K0 951 605 D
Component: LIN BACKUP HORN H08 9001

Subsystem 2 - Part No: 3C0 951 171 C
Component: Neigungssensor 004 0611

Subsystem 3 - Part No: 3C0 951 171 C
Component: Innenraumueberw.004 0611

No fault code found.

Address 52: Door Elect, Pass. Labels: 1K0-959-702-MIN3.lbl
Part No SW: 1K0 959 702 AC HW: 1K0 959 792 N
Component: J387 TUER-SG BT 1517
Revision: 72009005 Serial number: 00000318588512
Coding: 0000244
Shop #: WSC 00028 028 00001
VCID: 70E430BA63C2D9BE8E-8024

No fault code found.

VCDS
Self-Diagnosis Log
Friday,03,June,2016,18:18:01:25034
Page 9

VIN: XW8ZZZ3CZ9G000175 License Plate:

Address 53: Parking Brake Labels: 5N0-907-801.clb
Part No SW: 3C8 907 801 A HW: 3C8 907 801 A
Component: J540 EPB3 VW-10498 0003
Revision: 008 Serial number: 00000000006634
Coding: 0000057
Shop #: WSC 00028 028 00001
VCID: 285418DA9B92D17E16-807C

No fault code found.

Address 55: Headlight Range Labels: 5M0-907-357-V2.lbl
Part No SW: 5M0 907 357 C HW: 5M0 907 357 C
Component: AFS-Steuergeraet 0133
Revision: 00H04000 Serial number:
Coding: 2311169
Shop #: WSC 00028 028 00001
VCID: 346CFCAA575AA59EAA-8060

Subsystem 1 - Part No: 7L6 941 329 A Labels: 3D0-941-329.CLB
Component: AFS-Lst.-Modul l 0004
Coding: 00000035

Subsystem 2 - Part No: 7L6 941 329 A Labels: 3D0-941-329.CLB
Component: AFS-Lst.-Modul r 0004
Coding: 00000035

No fault code found.

Address 56: Radio (J503) Labels: 5M0-035-1xx-56.clb
Part No SW: 1K0 035 186 AA HW: 1K0 035 186 AA
Component: Radio RCD310 012 0028
Revision: 00000000 Serial number: VWZ1Z2H5292969
Coding: 0500040004
Shop #: WSC 00028 028 00001
VCID: 65CA51EE6C000C16ED-8030

No fault code found.

Address 62: Door, Rear Left Labels: 1K0-959-703-GEN3.lbl
Part No SW: 1K0 959 703 AB HW: 1K0 959 795 L
Component: J388 TUEER-SG HL 0308
Revision: 41004101 Serial number: 00000000390330
Coding: 0000208
Shop #: WSC 00028 028 00001
VCID: 70E430BA63C2D9BE8E-8024

No fault code found.

VCDS
Self-Diagnosis Log
Friday,03,June,2016,18:18:01:25034
Page 10

VIN: XW8ZZZ3CZ9G000175 License Plate:

Address 72: Door, Rear Right Labels: 1K0-959-704-GEN3.lbl
Part No SW: 1K0 959 704 AB HW: 1K0 959 794 L
Component: J389 TUER-SG HR 0308
Revision: 41004101 Serial number: 00000000392536
Coding: 0000208
Shop #: WSC 00028 028 00001
VCID: 71E235BE68C8D0B681-8024

No fault code found.

End------(Elapsed Time: 02:26)-----